



# NORTH BIHAR POWER DISTRIBUTION COMPANY LTD.

(Regd. Office :VidyutBhawan, Baily Road, Patna)

Office of the Director (Project)

Letter No :N-XIII/RDSS/VA/Motihari Circle-3118/2023 :...../  
CIN No.- U40109BR2012SGC018920

Dated...../  
Contact No.: +91-77638 15039  
E-mail :directorprojects.nbpdc@gmail.com

From,

**I. C. Yadav,**  
Director(Project)

To,

**M/s Vindhya Telelinks Limited,**  
Club 125, 6th floor, Tower A, Plot No- 3, 4 & 5,  
Sector 125, Noida, UP-201301.

**Sub:- Regarding Vendor approval of M/s Ruma Isolator Company, Howrah.**

- Ref:-**
- 1) NIT No.-28/PR/NBPDCL/2022
  - 2) NOA No.-246&247 dated 06.03.2023
  - 3) Your Lt.No.-VTL/NBPDCL/RDSS/Approval/Motihari/65 dated 17.10.2023
  - 4) Your Lt.No.-VTL/NBPDCL/RDSS/Approval/Motihari/41 dated 17.07.2023

Sir,

With reference to subject noted above, this is to inform that as per your request and submitted documents, vendor is hereby approved for supply of following items as per terms and conditions of NIT/LOA/Technical Specifications and other guidelines issued time to time by REC under RDSS Scheme.

| Sl. No. | Name of Firm and address   | Name of Material/Equipment  |
|---------|--|---|
| 1.      | M/s Ruma Isolator Company<br>6, Q Road, Howrah, West Bengal-<br>711105 | 1. 11 KV 200 Amp AB Switch<br>2. 12 KV 400 Amp AB Switch<br>3. 11 KV 200 Amp HG Fuse<br>4. GI Stay Set (16x1800 mm)<br>5. GI Earthing Pipe (40x3000 mm)<br>6. GI Coil Earthing<br>7. GI Earthing Spike<br>8. 11 KV Danger Board<br>9. 415 V Danger Board<br>10. Disc Hardware fitting for Weasel Conductor (Single bolted, T&C and B&S type)<br>11. Disc Hardware fitting for Rabbit Conductor (Double bolted, T&C type)<br>12. Disc Hardware fitting for Dog Conductor (3-bolted, T&C type)<br>13. GI Fabricated Steel Structure |

The validity of this vendor approval is exist till the validity of submitted type test certificate. Apart from this the Model GTP & Drawing of the aforesaid material has already been approved which is being attached with this letter for your ready reference.

The Vendor will have to fulfill the required criteria of SBD/IS code & various tests to be conducted during pre-dispatch inspection.

As per the provision of SBD & REC D.O. Lr. No. REC/RDSS/Quality Assurance / FY 2022-23/ D.no. 6268 dated 03.07.2023, there are penalty provisions for the equipment /material supplied by the Turnkey Contractor (TKC)/Manufacturer/ Supplier that failed during the inspection and testing as per IS which are briefed below:-

- I. In case, a material supplied by the TKC failed during the Pre-Dispatch Inspection (PDI) and also failed in the subsequent repeat inspection of the rectified/replaced material, a complete lot of material under inspection will be required to be replaced by the manufacturer/supplier.
- II. If in the subsequent inspection of the new lot, the material again fails the inspection/testing, the materials shall be rejected, and *approval of vendor/sub-vendor shall also be cancelled for all RDSS projects.*



The penalty provision in case the materials picked up from DISCOM/PD site/store and tested at NABL Laboratory fails:-

- I. The entire lot of materials/equipment supplied by the defaulting manufacturer shall be rejected. All costs related to the removal of such rejected materials and reinstating a fresh lot of materials shall need to be borne by the turnkey contractor without any cost implication to the power utility.
- II. Actions shall be taken against the *willfully defaulted manufacturer and turnkey contractor or both*.
- III. Sub-vendors/vendor registration of the manufacturer shall be discontinued in all the power utilities of the country for a period of 5 years including in the power utility concerned where this act is found.
- IV. Turnkey contractor shall be responsible for repetitive failures of materials in field testing in a turnkey contract. In such situations, registration of turnkey contractor firms shall be discontinued in all the power utilities of the country for a period of 5 years including in the power utility concerned where this act is found.

In case any adverse report with regard to material/vendor arises at any stage, NBPDCCL reserves the right of withdrawal of the approval of the vendor with retrospective effect. The turn-key contractor in such case will be fully responsible to replace the whole materials at their own cost immediately. Approval of vendor shall be rejected at any time if any adverse report is received from any government utility in India or BSPHCL and its any subsidiary companies. The decision of NBPDCCL in this regard will be final.

This approval however does not absolve you from your liabilities under specific contract.


Yours faithfully  
Sd/-

(I. C. Yadav)  
Director (Project)

Memo No.:.....258...../

Dated : 20.10.2013

Copy forwarded M/s JSP Projects Pvt. Ltd., Flat No.- 5, II<sup>nd</sup> Floor, III<sup>rd</sup> B-2, Nehru Nagar, Ghaziabad (UP)- 201001/M/s AshokaBuildcon Ltd.,S.No.-861, Ashoka House, Ashoka Marg, Vadala, Nashik-422011 / M/s Polycab India Ltd.,Polycab House, 771,PanditSatwalekar Marg, Mumbai / M/s NCC Ltd., NCC House, Survey no. 64, Madhapur, Hyderabad, 500081 / M/s Vaishno Associates Vidyut Projects LLP,H.O-14-15,3<sup>rd</sup> Floor, Gajraj Tower, Motilal Atal Road, Jaipur / M/s CABCON India Ltd., 1<sup>st</sup> Floor, The Terminus Building, BG-12, Action Area -1B, New Town, Kolkata-700156 / M/s Techno Power Enterprises Pvt. Ltd., INFINITY "THINK TANK" Tower II, 10<sup>th</sup> Floor Plot No. A3, Block-GP, Sector V, Salt Lake City, Kolkata -700091 (WB)for information and necessary action.

  
(I. C. Yadav)  
Director (Project)